

Department of Environmental Conservation

# New York State Report to the Regional Response Team

**New York State Department of Environmental Conservation** 

Kumar Patel, Reg. Spill Response Program, NYSDEC Region 2 (NYC) Office

June 18-19, 2018 – Monmouth County Fire Academy, N.J.

#### **Basic Stats – Calendar Year 2018**

- We are divided into 9 Regional Offices + Central Office in Albany
- NYSDEC received 12,836 spill reports total 1,670 in NY City
- We initiated 615 State funded emergency cleanups statewide
- Vessel sinkings (pleasure craft), vessel groundings, saddle tank spills, haz mat cargo events, home fuel spills, utility spills

gasoline in neighborhood sewers, etc.





## Container Ship DUBLIN EXPRESS

- 3/28/19- Vessel operators found bunker fuel leak through hull when it docked at Global Terminal
- Current cleanup involved oil residue removal under wharf at terminal



#### Gasoline Vapors – Greenpoint Residences (Part 1)

- 3/8/19 Residents at 214
- Green St. complain of periodic gas vapors in building
- Checked usual pathways negative vapors found on side
- of building away from adjoining gas station
- Arranged for air monitoring w/NYSDOH - Old pipe found on street side of trap - repaired







#### Gasoline Vapors – Greenpoint Residences (part 2)


- - We then received gas & sewer odor complaints a block north (Freeman St.) 4 homes investigated (187, 201, 210, 212)
- Homes had vapors in vicinity of sewer traps Owners directed to get sewer traps, et. al. fixed by plumber NYCDEP flushed sewer on Freeman 4/6/19
- DEC assisting with ventilation/sampling in two homes
- Related via sewer to Green St. Issue
- Sewer flushed/sludge banks emanating pet. vapors removed – pet vapors lessened in sewers and homes
  Removal of sludge alleviated vapors – homes cleared except for 212 Freeman (undergoing mold work)

#### Map of locations investigated by NYSDEC






#### **Sewer Map of Area**



#### L – Line Fuel Spill – Vapor Impact

- 2/5/19 Significant petroleum odors in two subway stations on L Line (along
- Metropolitan Ave., between Lorimer St. and Bushwick Ave, Brooklyn)
- DEC and NYCTA worked on abating vapors coming from oil pooling in drain trough between the tracks – ventilation done through sidewalk vents
- DEC conducted "phase 1" and used Spill Fund to place wells around point of oil seepage into tunnel at Bushwick and Metropolitan. We found abandoned #2 fuel tank as pet. source above subway.

Proposed Monitoring Well Map



#### Proposed Monitoring Well Map Approximate Subway Location (to be verified by NYCT)



#### **NYSDEC's Drone Fleet**

- 20 pilots trained - more coming

- Drones have cameras/sensors

- Used in S.I./Texas/Puerto Rico By DEC
- If need from DEC, contact Matt Franklin in Albany 518-402-9555





### "Spills 101" training course from DEC R-2

- Course given to waterway advocacy groups, agencies

- Given to Newtown Creek and Bronx River Alliances

- FDNY – Part of HMT training and also taught to FD Marine units

-Fosters understanding of 3 levels of gov't response ability OIL SPILL IDENTIFICATION, NOTIFICATION, AND RESPONSE PROCEDURES ("OIL SPILL 101")

> Randall Austin Supervisor, Spill Response Program New York State Department of Environmental Conservation Region 2 (New York City)

> > NYS Department of Environmental Conservation

OPPORTUNITY



Conservation

## **Thank You**

#### KUMAR PATEL

Assistant Engineer,

Spill Response Program NYSDEC Reg. 2

47-40 21<sup>st</sup> Street, LI City, NY

Hiralkumar.patel@dec.ny.gov 718-482-4900

#### Connect with us:

Facebook: www.facebook.com/NYSDEC Twitter: twitter.com/NYSDEC Flickr: www.flickr.com/photos/nysdec



